

INSPECTION REPORT

Work Order Number: 0024669	Site address of Tree: 3459 Warburton Highway WARBURTON VIC 3799	
Date of inspection: 19th January 2022 Correct date is 19 th January 2023 amended by SB	Melway: 290 C4	
Name: [REDACTED]	Address: [REDACTED]	Phone: [REDACTED]
Recommended action:		
<p>#1- Remove tree</p> <p style="text-align: center;">Reasons for recommended action:</p> <p>#1- The tree has co-dominant trunks with health and vigour that is typical for the species. The tree is stable in the ground with no evidence of any root plate instability. The tree is located in a gravel and asphalt carpark, and it is likely that ongoing minor compaction is affecting the root plate; however, no obvious deterioration to the health and vigour of the tree was noticed in the canopy at the time of the inspection.</p> <p>The primary union of the co-dominant trunks has split in the past on the north-western side from the top of the union (at approximately 1.7 metres) down to the basal area of the tree. Probing the split indicated substantial decay in the primary union and lower trunk of the tree. A small split in the primary union was also observed on the south-eastern side of the primary union. Two Sonic Tomographs were conducted on the primary union at 1 metre above ground and 1.5 metres above the ground to determine the structural integrity of the primary union. The two test results showed extensive decay and dysfunctional wood with minimal structural wood at the two test heights. It is interpreted that at the time of the inspection, the two cables previously installed between the co-dominant trunks are the providing the structural support for the primary union.</p> <p>A large torsional split was observed in the lower section of the western co-dominant trunk extending up the trunk from approximately 2.5 metres above the ground to 7 metres. A hollow opening was observed in the eastern trunk at approximately 5 metres above the ground. This hollow has developed from a past branch breakage point and is likely providing habitat for local fauna.</p> <p>Generally, the scaffold branches displayed good taper and well-formed branch unions. Previous branch breakages were observed in the canopy, but none of the remaining branches were assessed to have a high likelihood for failure. Deadwood in the canopy was minimal at the time of the inspection.</p> <p>Due to the significant amount of degradation to the structural integrity of the trunk and primary union, and the limited structural wood at the two test heights, it is recommended that the tree is removed.</p>		
Risk & works priority: #1- Moderate	Site conditions & equipment required: 40m EWP, chipper, traffic control for carpark	

Map:

Age: #1- Mature		Common name: #1- Mountain Grey Gum		Botanical name: #1- <i>Eucalyptus cypellocarpa</i>	
No. 1.	Height (m) 30+		Spread (m) 30		DBH (cm) 270
Roots condition: #1- Compaction			Trunk condition: #1- Poor (split co-dominant trunks primary union and extensive decay in the lower trunk and primary union, torsional split in western trunk)		
Limbs condition: #1- Fair (past branch breakages)			Foliage condition: #1- Good		
Amenity value: #1- High			Habitat: Part of habitat corridor: No Hollow bearing: No Native Fauna Use: Yes		
Distance to building (m): 30		Do branches overhang buildings? No		Targets Carpark, LV, service wires, footpath, road	
Company: ENSPEC Pty Ltd		Name: [REDACTED]		Date report written up: 24 th January 2022 Correct date is: 24 th January 2023 amended by SB	

Tree Location Details
Tree Number
Test Number & Location
Botanical Name
Common Name
Test Height
Tree Circumference

The Sonic Tomograph test result indicates the percentage of the test area that is sound (high density) wood, incipient wood (wood being altered by the fungus) or active fungus and decayed (low density) wood. The tree was previously tested at approximately the same height in June 2016 and the results of that test, and the recent test are:

	2016	2023
Sound wood	22%	12%
Incipient wood	9%	5%
Active fungus & decayed wood	69%	83%


The circumference of the trunk at the test height has increased by approximately 43 cm since the 2016 test, and it is acknowledged erosion of the soil at the base of the tree has lowered the ground level in the years between tests. Therefore, the current test height is lower on the trunk than the 2016 test.

Notwithstanding the change in test heights, comparing the two test results shows that the percentage of sound wood has decreased, and the percentage of active fungus and decayed wood has increased over the 6½ years since the last test in 2016.

The active fungus progressed further through the heartwood since the 2016 test causing extensive degradation to the structural integrity of the trunk at the test point. Additionally, the test result shows that the tension wood in the split primary union of the co-dominant trunks that traverses the test height from sensors 2-3 through to sensors 13-14 is totally dysfunctional.

The test result shows that there is some structural compression wood at the test height. At the test height, the test result shows at sensor 6 there is 28 cm of sound wood; at sensor 10 there is 17 cm of sound wood; and at sensor 20 there is 43 cm of sound wood. Furthermore, it is observed that new wood growth increments are occurring in the compression wood at sensors 5, 6, 19, 20, 21 and 22.

Carpark
1
1 of 2 – Middle of primary union
Eucalyptus cypellocarpa
Mountain Grey Gum
1000mm above ground level at sensor one
8630mm at test height



Tree Number**Test Number & Location****Test Height****Tree Circumference**

The Sonic Tomograph test result indicates 15% of the test area is sound (high density) wood. There is 5% of incipient wood (wood being altered by the fungus). The remaining 80% is active fungus and decayed (low density) wood.


The fungus in the test result is associated with the degradation seen in the lower test point. The split primary union of the co-dominant trunks traverses the test height from sensors 3-4 through to sensor 14-15.

The active fungus has spread through the heartwood reaching the outer trunk between sensors 2 and 4; between sensors 8 and 10; between sensors 12 and 15; and between sensors 23 and 24. The test result shows that the fungus has caused significant degradation to the structural integrity of the trunk and primary union of the tree.

The progression of the fungus at the test point has confined the structural wood is to the compression wood of the co-dominant trunks and primary union. At the test height, the test result shows at sensor 6 there is 45 cm of sound wood; at sensor 11 there is 18 cm of sound wood; at sensor 16 there is 24 cm of sound wood; and at sensor 21 there is 35 cm of sound wood. Furthermore, it is observed that new wood growth increments are occurring in the compression wood at sensors 6, 7, 11, 20 and 21.

1

**2 of 2 – top section of the primary union
1500mm above ground level at sensor one
8700mm at test height**



Photographs



The tree in location



The gravel & asphalt carpark surrounding the tree




The split in the primary union on the north-western side of the union



The smaller split in the south-eastern side of the primary union



The cables previously installed between the co-dominant trunks.



The hollow opening in the eastern co-dominant trunk



The lower part of the torsional split in the western trunk



The upper part of the torsional split in the western trunk